

Turning

The cutting data recommendations below are applicable to tough cemented carbide grades. These are necessary for operations in which impact may occur, such as when turning plate with gas-cut edges.

Carbide grade	P25 / C6	P35 / C6-C5	K20 / C2
feed rate, f_n [in / rev]	0.004 – 0.015 – 0.030	0.004 – 0.015 – 0.030	0.004 – 0.010
	Cutting speed, v_c [in/min]		
WELDOX 100	11200 – 7700 – 5700	9100 – 5900 – 3900	–
WELDOX 130	5100 – 3500 – 2800	4100 – 2600 – 1800	–
WELDOX 160	5100 – 3500 – 2800	4100 – 2600 – 1800	–
HARDOX 400	5100 – 3500 – 2800	4100 – 2600 – 1800	–
HARDOX 450	5100 – 3500 – 2800	4100 – 2600 – 1800	–
HARDOX 500	–	–	3900 – 3200

Formulas:

$$v_c = \pi \times D \times n$$

v_c = cutting speed [in/min]
 D = workpiece dia. [in]

$$n = \frac{v_c}{\pi \times D}$$


n = speed [rpm]
 $\pi = 3.14$

$$v_f = f_n \times n$$

v_f = feed rate [in/min]
 f_n = feed rate [in/rev]

At higher feed rates, lower the cutting speed.

Tool materials / Cemented carbide grades



This brochure has been written in cooperation with Sandvik Coromant AB and Dormer Tools AB. Granlund Tools AB has contributed pictures and cutting data for the section dealing with countersinking.

For further information, please get in touch with our Technical Customer Service Department.

The *Machining* brochure is included in a series of publications that offer advice and instructions for working on HARDOX and WELDOX plate. The other brochures in the series are *Welding*, *Bending/Shearing* and *Cutting*. Place your order for them with our Market Communication Department.





HARDOX[®]

WELDOX[®]

machining

SSAB
OXELÖSUND

Drilling
Countersinking
Tapping
Milling
Turning

HARDOX and WELDOX are registered trademarks. These steel grades are manufactured only by SSAB Oxelösund AB.

This brochure contains general suggestions and calculation models. SSAB Oxelösund AB hereby expressly disclaims any liability for their suitability for individual applications. It is the responsibility of the user of the brochure to adapt the recommendations contained therein to the requirements of individual applications.

HARDOX wear plate and WELDOX extra-high strength structural plate are steel grades that can be machined with high speed steel (HSS) or cemented carbide (CC) tools. This brochure includes our suggestions for cutting data (feeds and speeds) and the selection of tools. Other factors that should be taken into account in machining operations are also discussed. The proposals have been drawn up following our own tests on tools of various makes and in consultation with leading tool manufacturers.

TYPICAL PROPERTIES OF WELDOX AND HARDOX

	WELDOX 100	WELDOX 130	WELDOX 160	HARDOX 400	HARDOX 450	HARDOX 500
Tensile strength, R_m [ksi]	~ 125	~ 150	~ 195	~ 180	~ 205	~ 225
Hardness [HBW]	~ 260	~ 315	~ 430	~ 400	~ 450	~ 500



Drilling

Either high speed steel or cemented carbide drills can be used for drilling. The machine available and its stability determine the type of drill that should be employed. But whatever the machine type, it is vital to minimize vibrations.

Radial or column drilling machines

Recommendations for reducing vibrations and increasing the useful life of the drill:

- Minimize the distance from the drill to the column.
- Avoid wooden spacer blocks.
- Clamp the workpiece securely, and drill as close as possible to the spacer blocks.
- Minimize the distance between the drill tip and arm by using a short spindle and short drill.
- Just before the drill breaks through, disengage the feed for about a second. Play and elasticity in the machine could otherwise snap the drill tip. Re-engage the drill feed when the play/elasticity have ceased.
- Provide an abundant supply of coolant.



	WELDOX 100	WELDOX 130	WELDOX 160	HARDOX 400	HARDOX 450	HARDOX 500
v_c [in/min]	~ 710	~ 600	~ 280	~ 360	~ 280	~ 200
D [in]	Feed rate, f [in/rev] / Speed, n [rpm]					
1/4	0.004 / 900	0.004 / 750	0.002 / 360	0.002 / 460	0.002 / 360	0.002 / 260
3/8	0.004 / 575	0.004 / 475	0.004 / 220	0.004 / 290	0.004 / 220	0.003 / 130
5/8	0.006 / 400	0.006 / 325	0.006 / 150	0.006 / 190	0.006 / 150	0.005 / 85
3/4	0.009 / 300	0.009 / 235	0.008 / 110	0.009 / 150	0.008 / 110	0.007 / 65
1	0.012 / 240	0.012 / 195	0.010 / 90	0.012 / 110	0.010 / 90	0.009 / 50
1 1/4	0.014 / 200	0.014 / 165	0.012 / 75	0.014 / 90	0.012 / 75	0.010 / 45

	FACE MILLING				END MILLING			
	Coated CC		Cermet	Coated CC	CC		HSS-Co	
Grade	P40 / C5	P25 / C6	P20 / C6-C7	K20 / C2	K10 / C3-uncoated	K10 / C3-coated	P10 / C7-indexable insert	TiCN-coated
Conditions	unstable	average	stable	stable	stable	stable	stable	unstable
Feed rate (f_z)	0.004-0.008-0.012	0.004-0.008-0.012	0.004-0.008	0.004-0.008	0.0008-0.0040	0.0008-0.0080	0.0020-0.0080	0.0010-0.0035
Plate grade	Cutting speed, v_c [m / min]							
WELDOX 100	7700-5900-3700	8700-7100-5900	9400-7900	–	3900	7100	7700-5900	1600
WELDOX 130	3700-3000-2000	7900-6300-5100	8700-6700	–	3500	5100	5500-4700	700
WELDOX 160	–	5900-4700-4300	5900-4700	–	3500	3900	4300-3500	700
HARDOX 400	–	5900-4700-4300	5900-4700	–	3500	3900	4300-3500	700
HARDOX 450	–	5900-4700-4300	5900-4700	–	3500	3900	4300-3500	700
HARDOX 500	–	4700-3900	4700-3900	4700-3900	3500	3200	3500-2800	–

At higher feed rates, lower the cutting speed.

Formulas:

$$v_c = \pi \times D \times n$$

v_c = cutting speed [in/min]
 D = cutter diameter [in]

$$n = \frac{v_c}{\pi \times D}$$

n = speed [rpm]
 $\pi = 3.14$

$$f_z = \frac{v_f}{n \times z}$$

v_f = feed rate [in/min]
 f_z = feed rate per tooth [in/tooth]

$$v_f = f_z \times n \times z$$

z = number of cutter teeth

If problems should arise ...

Land wear
 Notch wear
 Cratering wear
 Plastic deformation
 Cutting edge build-up
 Comb cracks
 Small damage to the cutting edges (edge chipping)
 Insert failure
 Vibrations
 Poor surface finish
 Short useful life of HSS-Co cutters


Action and solutions ▲

Reduce the cutting speed
 Increase the cutting speed
 Reduce the feed rate per tooth
 Increase the feed rate per tooth
 Use a more wear resistant CC grade (see page 8)
 Use a tougher CC grade (see page 8)
 Use a coarse-pitch cutter
 Change the cutter position
 Avoid using a coolant
 Change over from HSS-Co to solid CC cutter
 Check the cutter set-up

Milling


SELECTION OF MILLING METHOD AND CUTTERS

To ensure rational production, milling cutters with cemented carbide inserts are recommended.




The following factors should be borne in mind when milling:

- Make certain that the workpiece is securely clamped.
- If the machine power is low, use a coarse-pitch cutter.
- If possible, avoid a universal head, since this weakens the tool mounting and power transmission.
- The width of cut in face milling should be about 75–80% of the cutter diameter (see figure to the right).
- When milling surfaces which are narrower than the diameter of the milling head, the milling cutter should be located eccentrically, so that as many teeth as possible will be in engagement.
- When milling a gas-cut edge, the depth of cut should be at least 0.1 inches, in order to avoid the hard surface layer of the cut edge (see graph).



Hardness profile of gas-cut edge, cut in air



More stable machine tools, such as boring mills and bed-type milling machines

For improved productivity, the benefits of cemented carbide drills should be put to use in modern and stable machines.


The choice is available between three main types of drills with cemented carbide cutting edges. The choice of drill type is dependent on the stability of the machine, the clamping of the workpiece, the hole diameter and the required tolerance. Always use the shortest possible drill.

Coolant

- Use the type of coolant intended for drilling.
- Rule of thumb for drilling with internal coolant passages: Coolant flow 5 gallons/min per inch drill diameter.


Solid cemented carbide drill

- Diameters from approx. 1/8 in.
- Close tolerances (high precision)
- Can be reground
- Sensitive to vibrations



Brazed cemented carbide drill

- Diameters from approx. 3/8 in.
- Close tolerances (high precision)
- Can be reground
- Less sensitive to vibrations than solid carbide.



Indexable insert drill

- Diameters from approx. 1/2 in.
- Offers high productivity
- Wider tolerance than the others (lower precision)
- Good economy



		WELDOX 100	WELDOX 130	WELDOX 160	HARDOX 400	HARDOX 450	HARDOX 500
Cutting speed, v_c [in/min] and Feed rate, f [in/rev]							
Solid cemented carbide	v_c	2000–2800	1600–2000	1200–1600	1400–1800	1200–1600	1000–1400
	f	0.004–0.007	0.004–0.007	0.004–0.006	0.004–0.006	0.004–0.006	0.003–0.005
Brazed cemented carbide	v_c	1600–2400	1600–2400	1200–1600	1400–1800	1200–1600	800–1200
	f	0.005–0.007	0.005–0.007	0.004–0.006	0.004–0.006	0.004–0.006	0.003–0.005
Indexable inserts	v_c	3900–4700	2800–3500	2000–4700	2400–3100	2000–2800	1600–2400
	f	0.004–0.007	0.004–0.007	0.002–0.006	0.002–0.006	0.002–0.006	0.002–0.005

If the drill diameter is small, select a lower feed rate within the specified range.

To calculate the speed of rotation from the recommended cutting speed:

Example for drill diameter $D = 5/8$ in and cutting speed $v_c = 3000$ in/min

$$\text{Speed, } n = \frac{v_c}{\pi \times D} = \frac{3000}{3.14 \times 5/8} = 1528 = \text{approx. } 1500 \text{ rpm.}$$

Formulas:

$$v_c = \pi \times D \times n$$

$$n = \frac{v_c}{\pi \times D}$$

$$v_f = f \times n$$

v_c = cutting speed [in/min]

D = drill diameter [in]

n = speed [rpm]

$\pi = 3.14$

v_f = feed rate [in/min]

f = feed rate [in/rev]

Drilling contd. ►

Drilling (contd.)

If problems should arise ...

- HSS drill tip deformed
- CC drill tip deformed
- Wear on the outside of the drill
- Holes oversize/undersize
- Chip build-up in the drill flutes
- Vibrations
- Small damage to the cut. edges (edge chipping)
- Asymmetrical holes
- Short useful life of HSS tool
- Short useful life of CC tool

Action and solutions ▲

- Adjust the drill setting.
- Increase the coolant flow rate, clean the filter and the coolant holes of the drill.
- Choose a tougher grade - see the figure on page 8.
- Reduce the feed rate.
- Increase the feed rate.
- Improve the stability by more secure work-piece clamping and reduced drill overhang.
- Check the guideline values of cutting data.
- Check that the right HSS or CC grade is used.
- Increase the cutting speed.
- Reduce the cutting speed.

Counterboring and countersinking

Spot-facing and countersinking are best done by means of countersinking tools which have replaceable cemented carbide inserts and a rotating pilot. Use coolant.



Counterbore with replaceable inserts and revolving pilot.



Conical countersink with replaceable inserts and revolving pilot.

	WELDOX 100 ¹	WELDOX 130	WELDOX 160	HARDOX 400	HARDOX 450	HARDOX 500
v_c [in/min]	2800–3900 ²	1600–2600 ²	800–2000 ²	1000–2800 ²	800–2000 ²	700–2000 ²
Feed rate, f [in/rev]	0.004–0.008	0.004–0.008	0.004–0.008	0.004–0.008	0.004–0.008	0.004–0.008
D [in]	Speed, n [rpm]					
$\frac{3}{4}$	1175–1675	670–1090	335–840	420–1175	335–840	285–840
1	930–1325	530–865	265–665	330–930	265–665	225–665
$1 \frac{3}{8}$	655–935	375–610	185–470	235–655	185–470	160–470
$1 \frac{5}{8}$	530–760	300–495	150–380	190–530	150–380	130–380
$2 \frac{1}{4}$	390–560	225–365	110–280	140–390	110–280	95–280

NOTE

1. Reduce the cutting data by about 30% in countersinking.
2. Always use a revolving pilot.

- 1) If chipbreaking problems should arise, feed in steps of 0.1 inches at a time.
- 2) If the machine power is low, select a cutting speed towards the lower end of the range.

		WELDOX 100	WELDOX 130
v_c [in/min]		~ 320	~ 280
D [in]	Feed rate f [in/rev]	Speed, n [rpm]	
5/8	0.002–0.008	170	150
3/4	0.002–0.008	130	120
1	0.003–0.012	100	90
1 3/8	0.003–0.012	70	70
1 5/8	0.003–0.012	60	50
2 1/4	0.003–0.012	40	40


HSS countersinking cutters with three cutting edges and equipped with a pilot can be used in the WELDOX steels tabulated below. An abundant flow of coolant is necessary.




Tapping

If the correct type of tap is used, holes can be tapped in all HARDOX and WELDOX steels. We recommend four-flute taps which can withstand the high torques necessary for tapping holes in hard materials. When HARDOX and WELDOX materials are tapped, thread oil or thread paste is recommended as lubricant.


In applications in which thread strength is not critical, a somewhat larger than standard hole diameter can be drilled (about 3% larger), in order to reduce the tap stresses during tapping. This will increase the useful life of the tap, above all when tapping holes in HARDOX and WELDOX 1100.



Tap for blind holes.




Tap for through holes.



NOTE

1. If uncoated taps are used, the cutting data should be lowered by 30%.
2. If tapping is carried out in NC machines, thread milling can be employed.



	HSS-Co (HSS-E) TiN or TiCN coated			HSS-Co (HSS-E) TiCN coated		
	WELDOX 100	WELDOX 130	WELDOX 160	HARDOX 400	HARDOX 450	HARDOX 500
v_c [in/min]	390	320	120	200	120	100
Size	Speed, n [rpm]					
3/8	320	255	95	160	95	80
1/2	265	210	80	130	80	65
5/8	200	160	60	100	60	50
3/4	160	125	45	80	45	40
1	130	105	40	65	40	30
1 1/4	105	85	32	50	32	25
1 5/8	75	60	22	35	22	20